

Gal Plumbing Industries LLC

**2034 Oakwell Ln
Katy, TX 77449**

(832) 906-1141

Licensed Master Plumber | Katy, TX #41065

Serving Katy, Houston & Surrounding Areas

galplumbingindustries.com

Gal Plumbing Industries LLC

**2034 Oakwell Ln
Katy, TX 77449**

(832) 906-1141

Licensed Master Plumber | Katy, TX #41065

Serving Katy, Houston & Surrounding Areas

galplumbingindustries.com

Gal Plumbing Industries LLC

**2034 Oakwell Ln
Katy, TX 77449**

(832) 906-1141

Licensed Master Plumber | Katy, TX #41065

Serving Katy, Houston & Surrounding Areas

galplumbingindustries.com

Slab Leak Detection Katy TX Gal Plumbing Industries Repair Options Slab leaks represent one of the more complex plumbing challenges for homeowners in Katy, TX, where concrete slab construction is the standard for residential foundations. When a copper supply line or drain line running beneath the slab develops a leak, the water can migrate through the concrete for weeks or months before manifesting as visible damage at the surface. The longer a slab leak goes undetected, the more costly the eventual repair tends to be, both for the plumbing work and for any foundation or interior repairs that become necessary. Gal Plumbing Industries LLC detects and repairs slab leaks for Katy homeowners, bringing licensed master plumber expertise to what is often the most technically demanding type of residential plumbing repair. The detection process uses a combination of pressure testing to confirm a leak is present and acoustic equipment to listen for the sound of water escaping from a pressurized line beneath the slab. By triangulating these signals, the team can identify the leak location with enough precision to minimize the concrete cutting required to access it. Repair options for slab leaks in Katy homes depend on the specific circumstances, including the location of the leak, the age and condition of the rest of the line, and the accessibility of the affected pipe section. Spot repair through a targeted concrete opening is appropriate when the rest of the system is in good condition and the leak is isolated. Rerouting the affected line through the interior of the home is an alternative that avoids additional concrete work. Full repiping is sometimes the most economical long-term choice when the copper lines beneath the slab are [Plumber Katy TX](#) showing widespread deterioration.

Gal Plumbing Industries LLC | 2034 Oakwell Ln, Katy, TX 77449 | +18329061141

Gal Plumbing Industries discusses all available options and their costs with the homeowner before committing to any approach, ensuring that the decision reflects the customer's priorities and budget rather than just the most convenient repair path. For slab leak detection in Katy, TX, call Gal Plumbing Industries LLC at +18329061141. Office at 2034 Oakwell Ln, Katy, TX 77449.